

February 1961

to
IMPROVEMENTS AND ALTERATIONS

**M.G. TWO-SEATER
(‘MGA’ TWIN CAM)**

This Index embodies all information issued up to and including Service Memorandum No. MG/339 and Parts List Amendment No. PMG/483.

SUBJECT	REFERENCE		SUBJECT	REFERENCE	
	MG/	PMG/		MG/	PMG/
GENERAL					
Adhesives			Carburettor		
—types recommended for various surfaces—difficulties if alternatives used in tropical climates	239		—damper—piston shortened for even running and maximum speed	264 (D.13)	347
Brake fluid			Clutch		
—essential use of approved grade	235		—component parts available ..	275	
Bumper bars			Connecting rods		
—removal of protective tape ..	261		—assemblies—importance of using similar weight—method of identifying assemblies of different weights	252	298
Fuel			—bearings—lead-tin type introduced—identification ..	309	
—octane value requirements—normal and competition use	238		Crankshaft		
Lack of power			—main bearings—lead-tin type introduced—identification ..	309	
—remedies for possible complaints	288		—modified—bosses at small-end to improve balance and strengthen big-end—heavier caps to suit	262	347
Paint			—oversize main bearing thrust washers available		475
—aluminium introduced ..		472	Cylinder block		
—new colours introduced ..		378	—rear main bearing—cap—modifications to prevent oil leaks		314
Service tools			Cylinder head		
—engine and clutch		337	—stronger valve springs introduced		426
—front suspension and steering		338	—valve guides—exhaust and inlet—oversize available ..		316
—gearbox		337	—valve guides—replacement engines—oversize type available—identification	259	
—gearbox front cover centralizer—fitting instructions ..	297	436	Cylinder head cover		
—rear axle and suspension ..		337, 338	—cables—lengthened		346
—spanner introduced for German requirements		311	Distributor		
—steering-wheel remover—universal pad added to suit all models	304		—clamping to correct misalignment and wear of driving gears	248	
Undersealing			—new type introduced to help prevent possible piston failure		
—necessity for masking ..	330		—campaign change	296, 301 (B.8)	419
POWER UNIT			Dynamo		
Air cleaner			—mountings—standardized ..		291
—incorporation of venturi ..	286	394	—pulley—diameter increased to reduce battery charging rate	237	
Assembly					
—(crankshaft, flywheel, and clutch)—discontinued—individual assemblies available—check after assembly ..	275				
Camshaft					
—bearing caps—fitting to avoid distortion	251				

February 1961

IMPROVEMENTS AND ALTERATIONS

**M.G. TWO-SEATER
(‘MGA’ TWIN CAM)**

This Index embodies all information issued up to and including Service Memorandum No. MG/339 and Parts List Amendment No. PMG/483.

SUBJECT	REFERENCE		SUBJECT	REFERENCE	
	MG/	PMG/		MG/	PMG/
Power Unit—continued			Replacement engines		
Engine mounting			—valve guides—identification of oversize types available ..	259 (A.19)	
—packing plate—added to in- crease clearance between starting dog and rack housing	(A.18)	292	Sparking plugs		
Fan			—modified for ordinary road use		310
—belt — lengthened to suit larger dynamo pulley to reduce battery charging rate	237		—new type—to improve heat condition at piston crown ..	253	346
Flywheel			Tappets		
—dowels — drilling holes to facilitate removal	267		—adjusting screw locknuts— modified to increase locking power		314
Gearbox			—clearances reduced	276	
—close-ratio type introduced		372	—lengthened to reduce possibi- lity of failure	253 (A.18)	339
—front cover bosses modified		425	Thermostat		
Half-speed shaft			—lower opening temperature type introduced		310
—drive gear tooth angle modi- fied to suit pump gear with more teeth	240 (A.18)	331	Timing cover		
Lack of power			—gasket—divided type available to obviate completely dis- mantling gear	257 (A.19)	
—remedies for possible com- plaints	288		Valve rocker cover		
Oil filter			—assembly — modified with better location for joint washer to improve sealing ..		349
—element—washing in petrol cancelled	335		Valves		
Oil pump			—springs—stronger type avail- able	310	
—drive spindle—number of teeth increased and tooth angles of half-speed shaft modified accordingly ..	240	331	Water pipes		
Pistons			—elbow—water inlet length- ened		346
—failures—compression ratio altered to suit lower octane fuel—accurate ignition set- ting essential	325	471, 483	—pipe — pump to elbow — straightened		346
—new distributor introduced to assist the prevention of piston failure — campaign change	296, 301	419	Water pump		
—rings—compression (chrome) —modified to reduce noise ..		347	—repair kits available		468
—rings — scraper — improved design	240, 278 (A.18)	331, 333, 371	TRANSMISSION AND REAR AXLE		
—rings — top — plain replaces chrome-plated	307	421, 471	Rear axle		
			—calliper unit assembly—im- proved design		348
			—hub extension modified ..		436
			—involute splines on axle shafts and differential gears intro- duced	278	371

February 1961

IMPROVEMENTS AND ALTERATIONS

M.G. TWO-SEATER
('MGA' TWIN CAM)

This Index embodies all information issued up to and including Service Memorandum No. MG/339 and Parts List Amendment No. PMG/483.

SUBJECT	REFERENCE		SUBJECT	REFERENCE	
	MG/	PMG/		MG/	PMG/
SUSPENSION, STEERING, ROAD SPRINGS AND WHEELS, SHOCK ABSORBERS, AND BRAKES					
Brakes			Hard top		
—disc—periodic examination of pads to maintain efficiency ..	332		—fibre-glass replaces metal—correct-type sidescreens essential—list of part numbers and models	338	
—master cylinder—damaged seals—essential use of correct fluid	235		Header tank		
—master cylinder—more suitable spring retainer introduced		457	—filler cap—modified to prevent loss of water	234	
—pipes—new-type unions introduced	331		—loss of water—remedy ..	234	
—wheel cylinder—damaged seals—essential use of correct fluid	235		—pressure valve—modified with separate bracket fixture to prevent vibration and water loss	234	
—wheel cylinder and piston assemblies (front)—improved design		349	Paint		
Front suspension			—aluminium introduced ..		472
—anti-roll bar now fitted as standard—reference made re earlier cars	278	371, 400	—new colours introduced ..		378
—bridge pipe—improved design		446	Petrol pump		
—calliper unit assembly—improved design		348	—rubber sleeve added to prevent ingress of water and dust		439
—spring spigot—modified to eliminate spring noise ..	240	314	Radiator		
Road wheels			—water loss—remote valve introduced to prevent water loss	(C.6)	318, 321
—hub caps—alternative type introduced		352	Seats		
CHASSIS, BODY, RADIATOR, PETROL AND EXHAUST SYSTEMS			—colour change		311
Body			—introduction of new features—normal and competition ..		376, 377, 379, 380, 382 to 384
—undersealing—masking necessary	330		Tonneau cover		
Engine mounting			—new type introduced ..		377, 378
—packing plate—added to increase clearance between starting dog and rack housing	(A.18)	292	—panel—improved stowage and seat adjustment ..	294	410
Fuel			Trim		
—octane value requirements—normal and competition use ..	238		—new features introduced ..		374 to 376, 379 to 382
			Windscreen		
			—contamination—methods of removal	329	
			ELECTRICAL EQUIPMENT		
			Battery		
			—cover available against ingress of dirt, etc. (optional extra)	249	345

February 1961

IMPROVEMENTS AND ALTERATIONS

**M.G. TWO-SEATER
(‘MGA’ TWIN CAM)**

This Index embodies all information issued up to and including Service Memorandum No. MG/339 and Parts List Amendment No. PMG/483.

SUBJECT	REFERENCE		SUBJECT	REFERENCE	
	MG/	PMG/		MG/	PMG/
Electrical Equipment—continued			Literature—continued		
Control box			Parts List Amendments Nos.		
—improved type introduced—			PMG/426, 432, 435, 436, 439		
essential to use correct re-			to 443, 446, 453 to 455, 466		
sistance	324		to 468, 470 to 473, 475, 477,		
			480, 483.		
Dipper			Service Tool Catalogue — Part		
—switch—repositioned to sim-			No. AKD770 (Second Edition).		
plify operation		370	All pages should bear the refer-		
			ence (30549).		
Distributor			Workshop Manual — Part No.		
—clamping to correct mis-			AKD926.		
alignment and wear of driving			The following have been issued		
gears	248		for the above Manual:		
—new type introduced to help			Additional Sheets—5; A.23; C.9;		
prevent possible piston failure			H.17; N.21, N.22.		
—camshaft change	296, 301	419	Amended Sheets—Issue No. 2—		
			General Information 5 to 8;		
Dynamo			A.7, A.8; C.1, C.2, C.5 to C.8;		
—mountings—standardized ..		291	D.1, D.2; E.9, E.10; F.1, F.2;		
—pulley—diameter increased to			H.7 to H.10, H.13 to H.16; J.1		
reduce battery charging rate	237	312	to J.4, J.7, J.8; K.1, K.2, K.9,		
			K.10; M.1 to M.6, M.9; N.3 to		
Harness			N.6, N.15, N.16; O.3, O.4;		
—new cables introduced ..		373, 382	S.3 to S.6, S.9, S.10.		
			Amended Sheets—Issue No. 3—		
Lack of power			1 to 4; General Data 5 to 7;		
—remedies for possible com-			General Information 11; A.5,		
plaints	288		A.6, A.11 to A.14; B.1 to B.8;		
			D.13; F.3, F.4, F.7, F.8; H.1,		
Lamps			H.2, H.5, H.6, H.11, H.12; K.7,		
—fog—relay introduced ..		455	K.8; M.7, M.8; N.17 to N.20;		
—head — introduced (North			P.3, P.4, P.7; S.1, S.2, S.7, S.8.		
America only)	(N.22)	395	Amended Sheets—Issue No. 4—		
—introduction of new features		373	General Data 1, 2; General		
			Information 9, 10; Mainte-		
Sparking plugs			nance Attention 1, 2; A.9, A.10,		
—modified for ordinary road			A.15, A.16, A.21, A.22; F.5,		
use		310	F.6; N.1, N.2; P.1, P.2, P.5,		
—new type—to improve heat			P.6; Key to Lubrication Chart;		
condition at piston crown ..	253	346	Lubrication Chart.		
			Amended Sheets—Issue No. 5—		
			Maintenance Attention 3, 4;		
			A.1, A.2, A.17 to A.20.		
			Amended Sheets—Issue No. 6—		
			General Data 3, 4.		
LITERATURE					
Driver's Handbook — Part No.					
AKD879B.					
Price List—Part No. AKD693.					
Supplements Nos. 1 to 29.					
Schedule of Repair Charges—					
Part No. AKD987A.					
Schedule of Repair Times—Part					
No. AKD986B.					
Service Parts List — Part No.					
AKDI296.					