CONFIDENTIAL

MG/253

SERVICE MEMORANDUM

13 May 1959

IMPORTANT MODIFICATIONS

<u>Parts List</u> <u>Amendment No.</u>

Road wheels

From Car No. 63577 - MGA

PMG/335

Improved design

Stronger road wheels fitted,

New wheels are interchangeable with those superseded except for slight difference in appearance.

Tappets

From Engine No. 1087 - MGA 'Twin-Cam'

PMG/339

To reduce possibility of tappet failure

Length of tappet increased to 1.5"

(38,10mm,).

Interchangeable in sets.

Sparking plugs

To improve heat condition at piston crown

Champion N5 plugs replaced by N3 type.

Interchangeable in sets only.

See Service Manager's letter dated 21 April

1959 for further details.