

CONFIDENTIAL

MG / 377

SERVICE MEMORANDUM

MGF / 81

1 August 1961


SERVICE TOOLS

Warning Light Bezel Spanner

Service Tool 18G670

Classification: Distributors B
 Dealers B

This tool has been introduced to enable brake warning light bezel nuts to be replaced without damage to the fascia panel.



Switch Bezel Spanner

Service Tool 18G671

Classification: Distributors B
 Dealers B

This tool has been introduced to enable the bezel nuts on ignition and lighting switches to be replaced without damage to the fascia panel.

